

## ECS Configuration Change Request

Page 1 of 1 Page(s)

<b>1. Originator</b> Byron V. Peters	<b>2. Log Date:</b> 04/01/03	<b>3. CCR #:</b> 03-0229	<b>4. Rev:</b>	<b>5. Tel:</b> 301/883-4077	<b>6. Rm #:</b> 2013	<b>7. Dept.</b> SE
<b>8. CCR Title:</b> Install SGI Patch Test Executable to Support BDS over Gigabit Ethernet						
<b>9. Originator Signature/Date</b> Byron Peters /s/ 4/1/03			<b>10. Class</b> II	<b>11. Type:</b> CCR	<b>12. Need Date:</b> 03/04/03	
<b>13. Office Manager Signature/Date</b> Carolyn Whitaker /s/ 4/1/03			<b>14. Category of Change:</b> Initial ECS Baseline Doc.		<b>15. Priority:</b> (If "Emergency" fill in Block 27). Emergency	
<b>16. Documentation/Drawings Impacted</b> (Review and submit checklist): Will be included in next appropriate patch release			<b>17. Schedule Impact:</b>		<b>18. CI(s) Affected:</b> STMGT	
<b>19. Release Affected by this Change:</b> 6A		<b>20. Date due to Customer:</b>		<b>21. Estimated Cost:</b> None - Under 100K		
<b>22. Source Reference:</b> <input checked="" type="checkbox"/> NCR (attach) <input type="checkbox"/> Action Item <input type="checkbox"/> Tech Ref. <input type="checkbox"/> GSFC <input type="checkbox"/> Other: ECSed37050						
<b>23. Problem: (use additional Sheets if necessary)</b> BDS has a problem with flow control when using Gigabit Ethernet. The driver sends the wrong error to the application which is ignored resulting in potentially bad data.						
<b>24. Proposed Solution: (use additional sheets if necessary)</b> SGI has released patch 5032 to fix this issue. Refer to page 2 for machines impacted. Tar file is on lemmings. cksum data: 2097849466 215040 patch5032.final.tar						
<b>25. Alternate Solution: (use additional sheets if necessary)</b> N/A						
<b>26. Consequences if Change(s) are not approved: (use additional sheets if necessary)</b> Continued performance deficit at GES DAAC.						
<b>27. Justification for Emergency (If Block 15 is "Emergency"):</b> Needed at GES DAAC as soon as possible						
<b>28. Site(s) Affected:</b> <input type="checkbox"/> EDF <input checked="" type="checkbox"/> PVC <input checked="" type="checkbox"/> VATC <input checked="" type="checkbox"/> EDC <input checked="" type="checkbox"/> GSFC <input checked="" type="checkbox"/> LaRC <input checked="" type="checkbox"/> NSIDC <input type="checkbox"/> SMC <input type="checkbox"/> AK <input type="checkbox"/> JPL <input type="checkbox"/> EOC <input type="checkbox"/> IDG Test Cell <input type="checkbox"/> Other						
<b>29. Board Comments:</b>			<b>30. Work Assigned To:</b>		<b>31. CCR Closed Date:</b>	
<b>32. EDF/SCDV CCB Chair (Sign/Date):</b>		<b>Disposition:</b> Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS				
<b>33. M&amp;O CCB Chair (Sign/Date):</b> Gary Gavigan /s/ 4/1/03		<b>Disposition:</b> <span style="border: 1px solid red; color: red;">Approved</span> App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS				
<b>34. ECS CCB Chair (Sign/Date):</b>		<b>Disposition:</b> Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ESDIS				

## ADDITIONAL SHEET

**CCR #:** 03-0229      **Rev:**      **Originator:** Byron V. Peters

**Telephone:** 301/883-4077      **Office:** SE

**Title of Change:** Install SGI Patch Test Executable to Support BDS over Gigabit Ethernet

**Machines Impacted:**

GSFC: g0spg01,g0spg07, g0spg10, g0spg11,g0acg01,g0dig06, g0drg01, g0drg02, g0drg04, g0drg05, g0icg01, g0icg02, g0mog01  
(when ready)

LP DAAC: e0spg01, e0spg05, e0acg11, e0dig06, e0drg11, e0drg12, e0icg11

NSIDC: n0acg01, n0dig06, n0drg01

LaRC: l0spg01, l0spg05, l0spg06, l0spg10, l0acg02, l0dig06, l0drg01

PVC: p0spg01, p0spg07, p0dig06, p0acg05, p0drg01, p0drg04, p0icg01, p0teg01

VATC: t1spg03, t1acg04, t1dpg06, t1drg03